


Zeri


5990982/00 TL1234G9-1GS




LICHTQUELLE LIGHTING SOURCE	230V~ 50Hz LED G9 Max. 5W	INKLUSIVE INCLUDED	
		NICHT INKLUSIVE NOT INCLUDED	✓


WERKZEUGE TOOLS		INKLUSIVE INCLUDED	
		NICHT INKLUSIVE NOT INCLUDED	
		NICHT NÖTIG NOT NECESSARY	✓

EISENWAREN HARDWARE	INKLUSIVE INCLUDED	
	NICHT INKLUSIVE NOT INCLUDED	
	NICHT NÖTIG NOT NECESSARY	✓



1



2

Replace failed lamps immediately by lamps of the same rated voltage and wattage to prevent overheating. Disconnect the lamp from the electrical supply and wait for it to cool down. Follow the indications on the drawing when changing the bulb.

If the external flexible cable or cord of this luminaire is damaged, it shall be exclusively replaced by the manufacturer or his service agent or a similar qualified person in order to avoid a hazard.

